

Circuit City – Gastonia NC [R06574] 11/21/06 Leak Investigation  
Carlisle CMD # 040747A / PO # SS 80013311



On 11/16/06 Carlisle SynTec notified TQM Roofing of a roof leak at the above referenced location. TQM Roofing investigated on 11/21/06.



On arrival Lori Roseman reported one leak over front entrance door behind register 2.

Circuit City – Gastonia NC [R06574] 11/21/06 Leak Investigation  
Carlisle CMD # 040747A / PO # SS 80013311



View of leak area as seen from the roof. Roof system was inspected, including the area at top of high wall, and three areas of damage were found in the TPO membrane. Damage was found 5', 15', and 60' from the leak area.



Close up view of one of the three areas of damage. This particular area appears to be a cigarette burn. All three areas were removed as a damaged membrane samples and are included with this report.

Circuit City – Gastonia NC [R06574] 11/21/06 Leak Investigation  
Carlisle CMD # 040747A / PO # SS 80013311



All three areas were cleaned and repaired permanently using reinforced TPO.



General view of two of the repairs.